


# DLA+ QUICKSTART GUIDE

## DLA+



- ① Close all other running applications
- ② Insert the JPRO® Fleet Service Software Bundle CD or the DLA+ Driver CD into your CD or DVD drive or download the latest DLA+ drivers from [www.JPROFleetProducts.com](http://www.JPROFleetProducts.com)
  - If using the software CD, the installation program will begin automatically. Click the Install DLA Drivers button to begin.
  - If using downloaded drivers, begin the installation process by running the file you just downloaded
- ③ Connect the diagnostic cable to the **Vehicle** port on the DLA+
- ④ Attach the diagnostic cable's connector to the diagnostic port on the vehicle
- ⑤ Plug the USB cable into the USB port on the PC
- ⑥ Connect the other end of the USB cable to the port labelled **Computer** on the DLA+
  - Windows displays the Found New Hardware Wizard
  - **NOTE:** If the Found New Hardware Wizard fails to start, be sure that the USB cable is pushed completely into the adapter's USB port
  - When asked to connect to Windows Update, select "No, not this time" and click Next
  - Select "Install the software automatically" and click Next
  - Click Finish to complete the installation
- ⑦ Your DLA+ is ready to use with your diagnostic application!

**OREGON**  
SYSTEMS  
[www.noregon.com](http://www.noregon.com)

**JPRO**®  
FLEET DIAGNOSTICS

[www.JPROFleetProducts.com](http://www.JPROFleetProducts.com)